Material Safety Data Sheet FW-88/FW-2

Complies with OSHA's Hazard Communication Standard 29 CFR 1910.1200.

DATE OF PREPARATION: November 19, 2004

GOODSON
Tools and Supplies for Engine Builders
156 Galewski Drive • P.O. Box 847 • Winona, MN 55987-0847
Toll-Free 1-800-533-8010 • Local 507-452-1830 • www.goodson.com

1. IDENTIFICATION

Part No. & Description: FW-88 / FW-2 Fluid Weld

2. COMPOSITION / INFORMATION ON INGREDIENTS

Ingredient, Technical Descp.	CAS Number	OSHA PEL	ACGIH TLV	% WT
n/a	n/a	na/	na/	n/a

3. HAZARDS IDENTIFICATION / IDENTITY INFORMATION

This product has been determined to be non-hazardous, in accordance with 29 CFR 1910, Subpart Z, Toxic and Hazardous Substances, Occupation Safety and Health Administration (OSHA) and Threshold Limit Values for Chemical Substances and Physical Agents i the Work Environment, American Conference of Governmental Industrial Hygienists (ACGIH)

4. PHYSICAL / CHEMICAL CHARACTERISTICS

Boiling Point: 180˚
Vapor Pressure : n/a
Vapor Density: n/a
Solubility in Water: 100%
Specific Gravity: n/a
Melting Point: n/a
Evaporation Rate: as water
Appearance and Odor: white / mild

5. REACTIVITY DATA

Stability: Stable
Incompatibility (materials to avoid): none
Hazardous Decomposition or By-products: none
Hazardous Polymerization: will not occur

6. FIRE AND EXPLOSION HAZARD

Flash Point: none - self extinguishing
Flammable Limits: n/a
Extinguishing Media: non-flammable
Special Firefighting Procedures: n/a
Unusual Fire & Explosion Hazards: n/a

7. HEALTH HAZARD DATA

Route of Entry: Inhalation? Yes Skin? Yes Ingestion? n/a
Health hazards (Acute & Chronic): None special. Do not ingest. Avoid eye contact. Follow common safety practices
Carcinogenicity: NTP? no **IARC Monographs?** no **OSHA Regulated?** no
Signs & Symptoms of Exposure: None special, except eye irritant
Medical Conditions Generally Aggravated by Exposure: None known
Emergency and First Aid Procedures: In case of eye contact, flush immediately with copius amounts of running water for 15 minutes. Get prompt medical attention for possible eye irritation. Skin contact: wash with water.

8. PRECAUTIONS FOR SAFE HANDLING AND USE

Steps to be taken in case material is released or spilled: Flush with water to sewer
Waste Disposal Method: Dilute 1 part to 100 parts water and flush through sewer
Precautions To Be Taken In Handling and Storage: Do not ingest. Avoid eye contact
Other Precautions: none

8. CONTROL MEASURES

Respiratory Protection (Specify Type): None required. Not volatile
Ventilation: Local Exhaust: n/a
Mechanical (General) n/a
Special: n/a
Other: n/a
Protective Gloves: no
Eye Protection: Normal eye protection for chemical use
Other Protective Clothing or Equipment: none
Work / Hygienic Practices: None special

© 2004 Goodson Shop Supplies